


CORNER RECORD

Document Number 99-192

City of RIVERSIDE County of RIVERSIDE, California

Brief Legal Description LOT 10, OF R.S. 2/116 IN SECTION 21, T.3 S., R.5 W., S.B.M.
(Include: Sec., Twp., Rge., and Meridian or Rancho)



CORNER TYPE

- ☐ Government Corner
☐ Meander
☐ Rancho
☐ Date of Survey MAY 12, 1999

- ☐ Control
☒ Property
☐ Other

COORDINATES (OPTIONAL)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - ☐ Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Centerline and rear monuments were recovered to enable re-establishment of front Lot corners, as shown on page
2 of 2.


A description of the physical condition of the monument as found and as set or reset:

See Page 2 of 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on MAY 25, 19 99.

Signed Joseph N. Beeler L.S. or R.C.E. Number 4055



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 6, 19 99.

And examined and filed July 19, 19 99.

Signed Michael C. Parks Title Senior Land Surveyor



County Surveyor's Comment _____

THE FILING OF THIS CORNER RECORD
DOES NOT RELIEVE THE SURVEYOR
FROM ANY RESPONSIBILITY OF THE
FILING OF A RECORD OF SURVEY

99-203